



Making a difference today  
for our world tomorrow



The Howard Johnson Hotel Kitchener/Conestoga has 102 guest rooms.

Back in June 2010 Hydroflow installed a C60 for the main water use and a S44 for the laundry. This resulted in a complete elimination of the old softeners which were stuck on regeneration, costing an extreme amount of money to operate.

Since the success Hydroflow returned to evaluate the Pool which required the heater to be serviced every few weeks due to the buildup of limescale.

To address this problem we installed a J62, within a few days there was evidence of small white particles resting in the bottom of the pool, this was the broken down accumulation that had gathered in the pool heater. (The heater no longer needs to be serviced due to limescale blockages and the pool clarity is evident).



Due to the diligence and confidence from Kam Patel (Manager)  
Who sourced our products in an effort to resolve his dilemmas?  
The Howard Johnson in Kitchener has become a much Greener place.

160 Saunders Road—Unit 4 Barrie Ontario L4N 9A4 TEL 705-739-3569 Fax 705-739-0640  
Hydroflow Canada inc is registered in Ontario Canada. Registration No.814523825

[www.hydroflowcanada.com](http://www.hydroflowcanada.com)